Operator: LIBERTY ENERGY (MID-STATES) CORP D/B/A LIBERTY UTILITIES - CENTRAL Operator ID		
Inspection Date(s): 4/21/2016 (Half) Man Days		
Inspection Unit: Virden		
Location of Audit: Virden		
Exit Meeting Contact: Scott Etter		
Inspection Type: Standard Inspection - Field Audit		
Pipeline Safety Representative(s): Jim Watts		
Company Representative to Receive Report: David Hinds, Michael Beatty, Ron Snider		
Company Representative's Email Address: david.hinds@libertyutilities.com, mike.beatty@libertyutilities.com, Ronald.Snider@libertyutilities.com		

Headquarters Address Information:	2751 N. High	
	Jackson, MO 63755	
	Emergency Phone#: (855) 644-8134	
	Fax#:	
Official or Mayor's Name:	Michael Beatty	
	Phone#: (573) 755-0108	
	Email: mike.beatty@libertyutilities.com	
Inspection Contact(s)	Title	Phone No.
Les Smith	Manager Operations	(618) 699-4615
Scott Etter	Field Supervisor	

	CUSTOMER METER & REGULATOR	Status
Category Comment:	<u>.</u>	
This was not applicable to	o this audit and was not reviewed as part of this inspection.	
[192.353(a)]	Is the customer meter and regulator installed in a readily accessible location and protected from corrosion and other damage, including if installed outside a building, vehicular damage that may be anticipated?	Not Checked
[192.355(b)(1)]	Is the customer regulator vent rain and insect resistant?	Not Checked
[192.355(b)(2)]	Is the customer regulator vent located where gas from the vent escapes freely into the atmosphere and away from building openings?	Not Checked
[192.355(b)(3)]	Is the vent protected from damage caused by submergence in areas of flooding?	Not Checked

[192.357(a)]	Is the customer meter and regulator installed to minimize anticipated stresses upon connecting piping?	Not Checked
[192.357(d)]	Is a customer regulator that might release gas vented to the outside atmosphere?	Not Checked
[192.359(a)]	Is the meter operating pressure within the allowable limits of the meter case rating?	Not Checked
[192.365(a)]	Is the service line valve upstream of the regulator or meter?	Not Checked
[192.365(c)]	Is the underground service line valve located in a curb box or standpipe that allows for ready operation?	Not Checked
[192.727(d)][192.727(d)]	When service to the customer has been discontinued has the proper method been utilized to prevent unauthorized usage?	Not Checked
	CATHODIC PROTECTION	Status
Category Comment:		
Level of CP was not reviewed	as part of this inspection.	
[192.463(a)]	Is the applicable cathodic protection criteria contained in Appendix D of this part being followed?	Not Checked
[192.465(a)]	Were pipe to soil readings taken?	Not Checked
[192.465(b)]	Were rectifier installations inspected?	Not Checked
[192.465(a)]	Were isolated mains/services tested?	Not Checked
[192.465(c)]	Were critical/non critical bonds tested?	Not Checked
[192.467(a)]	Is electrical isolation provided by use of insulated meter spud, valve, union, or flange?	Not Checked
[192.467(c)]	Were casings installations tested for electrical isolation?	Not Checked
[192.479(a)]	Is the above ground piping coated or painted as required?	Not Checked
[192.479(c)]	Is the pipeline free of corrosion or pitting?	Not Checked
DAMAGE PREVENTION		Status
[192.614]	Does the operator have a valid notification of planned excavation activities?	Not Applicable
General Comment:	<u> </u>	
There were no current notificat	tions of planned excavation for the site inspected.	
[265.40(a)]	Did the operator complete the locating activities in the specified timeframe?	Not Applicable
General Comment:	·	
There were no current notificat	tions of planned excavation for the site inspected.	
[192.614(c)(5)]	Were temporary markings made in accordance with the operator's Operation and	Not Applicable

	Maintenance Manual?	
General Comment:		
There were no current notif	ications of planned excavation for the site inspected.	
[192.707(a)(1)]	Are line markers placed and maintained as close as practical over each buried main and transmission line located at each crossing of a public road and railroad?	Satisfactory
General Comment:		
	erved present at the crossing of State Route 104 and Hunley Road and at the crossing of King Road on the west side south of the water crossing down to King Road.	west side of State Route 4.
[192.707(a)(2)]	Are line markers placed and maintained as close as practical over each buried main and transmission line located wherever necessary to identify the location of the transmission line or main to reduce the possibility of damage or interference?	Satisfactory
General Comment:		
Line markers were present	at the water crossing inspected as part of this audit.	
[192.707(c)]	Are line markers placed and maintained as close as practical over each main and transmission line located above ground?	Not Applicable
General Comment:	<u> </u>	
There was no above ground	d main in the vicinity of this inspection.	
[192.707(d)(1)]	Do the operator's line markers contain the following information: The following must be written legibly on a background of sharply contrasting color on each line marker: The word "Warning," "Caution," or "Danger" followed by the words "Gas (or name of gas transported) Pipeline" all of which, except for markers in heavily developed urban areas, must be in letters at least 1 inch (25 millimeters) high with ¼ inch (6.4 millimeters) stroke?	Satisfactory
General Comment:	<u> </u>	
The pipeline markers prese sided Tri-View Marker.	ent utilized the wording "Caution" Gas Pipeline in yellow and black lettering using quarter inch stroke on a wi	hite background on a three
[192.707(d)(2)]	Do the operator's line markers contain the following information: The following must be written legibly on a background of sharply contrasting color on each line marker: The name and phone number (including area code) of the operator where the operator can be reached at all times?	Satisfactory
General Comment:	<u>. </u>	
The marker label included t	their emergency phone number.	
PRESSU	RE LIMITING AND REGULATING DEVICES (MECHANICAL)	Status
Category Comment:		
Pressure regulating and lim	niting installations were not inspected as part of this audit.	

[192.739(a)(4)]	Was each pressure limiting station, relief device (except rupture discs), and pressure regulating station and its equipment subjected at intervals not exceeding 15 months, but at least once each calendar year, to inspections and tests to determine that it is properly installed and protected from dirt, liquids, or other conditions that might prevent proper operation.?	Not Checked
[192.317(b)]	Is each above ground transmission line or main protected from accidental damage by vehicular traffic or other similar causes?	Not Checked
[192.741(a),192.741(c)]	Were telemetering and/or recording gauges inspected for abnormally high or low pressure indications?	Not Checked
[192.743(a)]	Is overpressure protection provided on the pipeline down stream of the take point?	Not Checked
[192.199(d)]	Were the pressure relief or pressure limiting devices inspected to determine if the support was made of noncombustible material?	Not Checked
[192.199(e)]	Were the pressure relief or pressure limiting devices inspected to determine if the discharge stacks, vents, or outlet ports were designed to prevent accumulation of water, ice, or snow, and located where gas can be discharged into the atmosphere without undue hazard?	Not Checked
[192.199(h)]	Was each valve, designed to isolate the system under protection from its source of pressure, secured to prevent unauthorized operation of any stop valve that will	Not Checked
	make the pressure relief valve or pressure limiting device inoperative?	
		Status
Category Comment:	make the pressure relief valve or pressure limiting device inoperative?	Status
Category Comment: Valve installations were not ins	make the pressure relief valve or pressure limiting device inoperative? VALVE MAINTENANCE	Status
	make the pressure relief valve or pressure limiting device inoperative? VALVE MAINTENANCE	Status Not Checked
Valve installations were not ins	wake the pressure relief valve or pressure limiting device inoperative? VALVE MAINTENANCE spected as part of this audit. Were the valves readily accessible and was the operator able to access the	
Valve installations were not ins	wake the pressure relief valve or pressure limiting device inoperative? VALVE MAINTENANCE spected as part of this audit. Were the valves readily accessible and was the operator able to access the valve with the appropriate valve wrench?	Not Checked
Valve installations were not ins [192.747(a)] Category Comment:	wake the pressure relief valve or pressure limiting device inoperative? VALVE MAINTENANCE spected as part of this audit. Were the valves readily accessible and was the operator able to access the valve with the appropriate valve wrench?	Not Checked
Valve installations were not ins [192.747(a)] Category Comment: Odorization levels were not re-	make the pressure relief valve or pressure limiting device inoperative? VALVE MAINTENANCE spected as part of this audit. Were the valves readily accessible and was the operator able to access the valve with the appropriate valve wrench? ODORIZATION OF GAS	Not Checked
Valve installations were not ins [192.747(a)] Category Comment: Odorization levels were not re [192.625(a)]	make the pressure relief valve or pressure limiting device inoperative? VALVE MAINTENANCE spected as part of this audit. Were the valves readily accessible and was the operator able to access the valve with the appropriate valve wrench? ODORIZATION OF GAS viewed as part of this inspection.	Not Checked Status
Valve installations were not ins [192.747(a)] Category Comment: Odorization levels were not rev [192.625(a)] [192.625(e)]	make the pressure relief valve or pressure limiting device inoperative? VALVE MAINTENANCE spected as part of this audit. Were the valves readily accessible and was the operator able to access the valve with the appropriate valve wrench? ODORIZATION OF GAS viewed as part of this inspection. Was the odor intensity level readily detectable at or below 1/5th LEL?	Not Checked Status Not Checked
Valve installations were not ins [192.747(a)] Category Comment: Odorization levels were not rev [192.625(a)] [192.625(e)]	make the pressure relief valve or pressure limiting device inoperative? VALVE MAINTENANCE spected as part of this audit. Were the valves readily accessible and was the operator able to access the valve with the appropriate valve wrench? ODORIZATION OF GAS viewed as part of this inspection. Was the odor intensity level readily detectable at or below 1/5th LEL? Was the Odorization equipment and tank levels inspected?	Not Checked Not Checked Not Checked
Valve installations were not ins [192.747(a)] Category Comment: Odorization levels were not rev [192.625(a)] [192.625(e)]	make the pressure relief valve or pressure limiting device inoperative? VALVE MAINTENANCE spected as part of this audit. Were the valves readily accessible and was the operator able to access the valve with the appropriate valve wrench? ODORIZATION OF GAS viewed as part of this inspection. Was the odor intensity level readily detectable at or below 1/5th LEL? Was the Odorization equipment and tank levels inspected? Was the operator's equipment calibrated as required?	Not Checked Status Not Checked Not Checked Not Checked
Valve installations were not ins [192.747(a)] Category Comment: Odorization levels were not rev [192.625(a)] [192.625(e)] [192.625(f)] Category Comment:	make the pressure relief valve or pressure limiting device inoperative? VALVE MAINTENANCE spected as part of this audit. Were the valves readily accessible and was the operator able to access the valve with the appropriate valve wrench? ODORIZATION OF GAS viewed as part of this inspection. Was the odor intensity level readily detectable at or below 1/5th LEL? Was the Odorization equipment and tank levels inspected? Was the operator's equipment calibrated as required?	Not Checked Status Not Checked Not Checked Not Checked
Valve installations were not ins [192.747(a)] Category Comment: Odorization levels were not rev [192.625(a)] [192.625(e)] [192.625(f)] Category Comment:	were the valves readily accessible and was the operator able to access the valve with the appropriate valve wrench? ODORIZATION OF GAS Was the odor intensity level readily detectable at or below 1/5th LEL? Was the operator's equipment and tank levels inspected? TRANSMISSION	Not Checked Status Not Checked Not Checked Not Checked

[192.719(a)]	Is pre-tested transmission pipe inventory maintained for use in an emergency?	Not Applicable
[192.179(c)]	If blow down activities were observed, were the blow down valves properly sized to allow the transmission pipeline to vent as rapidly as practicable and did the blow down vent freely to atmosphere away from any hazards?	Not Applicable
	MARKING OF MATERIAL	Status
Category Comment:		
Marking of materials w	as not reviewed as part of this inspection.	
[192.63(a)]	Does the operator's components and pipe contain the required markings?	Not Checked
OPERATOR QUALIFICATION		Status
Category Comment:		
No covered tasks were	observed during the inspection.	
Was a PHMSA Fo	rm 15 Operator Qualification Field Inspection Protocol Form completed?	No